
| CITY OF BALTIMORE WET W SMOKE AND DYED W | Page / of <u>3</u> | |
|---|-------------------------------|-----------------------------|
| Sewershed: PATAPSCO | Company: Savin Engineers | Date: 9-22-09 |
| Test to be Performed: | Ground Condition: | Supervisor: Joe Mirabito |
| Smoke: X Dyed Water: | Dry: X Damp: Wet: | |
| Manhole ID: <u>54362</u> _ 605 m 4. | Test ID: _ \$ / 0 4 / - 0 6 2 | Notifications Made: |

Field Sketch: (Show All Manholes with Numbers, Blower Placement Location, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photograph Numbers)



| | | ALTIMORE \ OKE AND D | | | | ENT DECRE | E | Page 2 | of <u>3</u> |
|---|-------------------------------------|--------------------------------------|---------|----------|--------------|--|-------------|---------------------------------------|-------------|
| Sewer | shed: <u>PATA</u> | PSCO | | Compan | y: <u>SA</u> | VIN | | Date: 9/2 | 2/09 |
| Test to be Performed: Smoke: X Dyed Water: | | Ground Condition: Dry: X Damp: Wet: | | | | Supervisor: JAM | | | |
| Manhole ID: S43G2 005MH | | Test ID: <u>\$1041-062</u> | | | | Notifications Made: X (Residents, Fire, 311) | | | |
| | Sketch: (Showons, Street Nam | | | | | | _ | | |
| Defect | | | | Source | | | Drainage | · · · · · · · · · · · · · · · · · · · | Photo |
| No. | | Address | | Туре | Location | Sector | Area | Severity | Number |
| 1 | NEAR 4300 | WEST BAY | AVE. | 1 | 11 | 1 | 500 | 4 | P01 |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | OBSER\ | ATION | CODES | | | |
| | Source Type | Location | Sector | Severity | | Source Type | Location | | |
| 01 | Main Sewer | Paved Concrete | Public | No Smoke | 10 | MH Frame Seal | Non-Paved | | |
| 02 | Service Line | Paved Asphalt | Private | Trace | 11 | Storm Drain | Field/Woods | | |
| 03 | Cleanout | Paved Other | | Moderate | 12 | Catch Basin/Inlet | Alley | | |
| 04 | Downspout | Driveway | | Major | 13 | Storm Manhole | Golf Course | | |
| 05 | Area Drain | Sidewalk | | | | Storm Ditch | Other | | |
| 06 | Driveway Drain | Curb | | | 15 | Excavation | | | |
| | Stairwell Drain | Yard- Front | | | 16 | Other | | | |
| | Foundation Drain | Yard-Back | | | | | | | |
| 09 | Building Interior | Yard- Side | | | | | | | |

| CITY OF BALTIMORE WET W SMOKE AND DYED W | Page <u>3</u> of <u>3</u> | |
|---|---------------------------|-----------------------------|
| Sewershed: PATAPSCO | Company: Savin Engineers | Date: 9/22/09 |
| Test to be Performed: | Ground Condition: | Supervisor: Joe Mirabito |
| Smoke: X Dyed Water: | Dry: X Damp: Wet: | |
| | | Notifications |

Field Sketch: (Show All Manholes with Numbers, Blower Placement Location, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photograph Numbers)



S1041-062-OB01-P01